

# Golf Course Maintenance Building No.2

Herrick Archives Building 233

## A. IDENTIFICATION & LOCATION

### 1. Name

1.1 Never officially named by Board of Trustees action.

1.2 Alternate names noted:


Maintenance Building No. 2 at Golf Course

Service Building

### 2. Location

2.1 Located at 1467 McCoy Road. See map below. (Originally 1370 McCoy Road. Changed May 19, 1969).

2.2 For greater detail, see Sheet GC 7 in the book of campus maps in the University Archives.



For identification of other buildings shown, see Appendix A.

### 3. General Description

#### 3.1 Type of construction:

Metal skin on steel frame.

#### 3.2 No. of stories:

One.

#### 3.3 Increments of construction:

No additions.

#### 3.4 Present area of building as shown in inventory records of Division of Campus Planning:

5,834 sq. ft. gross; 5,374 sq. ft. net assignable

3.5 Volume of building:

86,882 cu. ft. (PP).

## B. PLANNING & CONSTRUCTION

1. On July 14, 1961 the Board of Trustees approved the plans and related documents prepared by W. E. Linch and authorized the solicitation of bids by contractors.

2. Bids were received on September 18, 1961.

3. On October 6, 1961 the Board of Trustees awarded contracts to the following contractors:

General: Ruscilli Construction Company

Electrical: Eastmoor Electric Company, Inc.

Heating and ventilating: Columbus Heating and Ventilating Company

Plumbing: Grif M. Lewis, Inc.

4. Completion and occupancy:

The building was assigned for use on April 6, 1962 (P).

## C. PHOTOGRAPHS

1. In Photoarchives:

X7373

X7374

John H. Herrick  
November 19, 1975